

## County Surveyor's Record, Douglas County, Oregon

- 30 -

## Subdivisions of T. 23 S., R. 9 W., W.M.

## CHAINS

- 54.75 A stream, 4 lks. wide, course S., 300 ft below  $\frac{1}{4}$  sec. cor.
- August 26: At this point, I set off 10\*12.5'N. on the decl. arc; and at 12<sup>h</sup> M, l.m.t., I observe the sun on the meridian; the resulting lat. is 43\*32'.
- Begin to ascend.
- 59.90 A Fir, 80 ins. diam., on line, which I mark with 2 notches on E. and W. sides.
- 61.25 The ascent of E. slope of mountain becomes steeper.
- 72.00 Top of dividing ridge, bears N. and S., 350 Ft. above stream; begin a very steep descent of SW. slope of mountain.
- 80.00 A point, 150 ft. below top of ridge. I set a sandstone 24 x 16 x 4 ins., 18 ins. in the ground for cor. of secs. 25, 26, 35 and 36, marked with 1 notch on S. and E. edges, from which,
- A Fir, 17 ins. diam., bears N.61\*E., 28 lks., dist. marked T 23 S R 9 W S 25 B T.
- A Fir, 16 ins. diam., bears S. 41\*E., 27 lks., dist. marked T 23 S R 9 W S 36 B T.
- A Fir, 16 ins. diam., bears S.3\*W., 22 lks., dist. marked T 23 S R 9 W S 35 B T.
- A Fir, 20 ins. diam., bears N.80\*W., 44 lks. dist. marked T 23 S R 9 W S 26 B T.
- Land, mountainous.
- Soil, gravelly and rocky; 3rd and 4th rates.
- Timber, Fir, Cedar, Hemlock, Laurel.
- Underbrush, dense, of Fir, Hazel, Vine-maple.
- Mountainous and heavily timbered land and land covered with a dense undergrowth.
- 80.00 chains.