

## County Surveyor's Record, Douglas County, Oregon

- 43 -

Subdivisions of  $\frac{1}{4}$ . 23 S., R. 9 W., W.M.  
same Deputy and Contract.

## CHAINS

46.97 The cor. of secs. 8, 9, 16 and 17; 100 ft. above  $\frac{1}{4}$  sec.  
cor.

Land, mountainous

Soil, clayey loam; 2nd rate.

Timber, Fir, Hemlock, Cedar, Maple, Alder.

Undergrowth of Salmonberries and Huckleberries.

Mountainous and heavily timbered land.

46.97 and 0.73 chs.

September 7, 1898.

Secs. 25, 26, 35 and 36.

S.0\*1' E. on a random line bet. secs. 35 and 36.

40.00 Set temp.  $\frac{1}{4}$  sec. cor.

80.20 Intersected S. bdy. of Tp. 45 lks. E. of cor. of secs.  
35 and 36 (described on page 5 of exterior lines)

N.0\*20'E. on true line bet. secs. 35 and 36.

Descend a N. slope of mountain, covered heavily with  
large fir and hemlock timber, dense undergrowth of  
huckleberries and vine-maple.

30.80 N. Fork of Lake Creek, 10 lks. wide, course W., 300 ft  
below sec. cor.

Begin to ascend a W. slope of mountain covered heavily  
with same timber.

40.20 Set an Alder post, 3 ft. long, 3 ins. sq., 24 ins. in  
the ground for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  S 35 on W. face,  
36 on E. face, from which,

A Fir, 24 ins. diam., bears N.25\*E., 37 lks. dist.  
marked  $\frac{1}{4}$  S 36 B T.

An Alder, 6 ins. diam., bears N.67\*W., 6 lks. dist.  
marked  $\frac{1}{4}$  S 35 B T.

This cor. stands 180 ft. above creek.

Continue the ascent of W. slope of mountain, heavily  
timbered.