

## County Surveyor's Record, Douglas County, Oregon

- 45 -  
 Subdivisions of E. 23 S., R. 9 W., W.M.  
 same Deputy and Contract.

CHAINS

ground for cor. of secs. 23, 24, 25 and 26, marked with  
 1 notch on E. and 2 notches on S. edges; from which,  
 A Fir, 20 ins. diam., bears N.61\*E., 19 lks. dist.  
 marked T 23 S R 9 W S 24 B T.  
 A Fir, 24 ins. diam., bears S.33\*E., 80 lks. dist.  
 marked T 23 S R 9 W S 25 B T.  
 A Fir, 20 ins. diam., bears S.42\*W., 13 lks. dist.,  
 marked T 23 S R 9 W S 26 B T.  
 A Fir, 30 ins. diam., bears N.24\*W., 12 lks. dist.,  
 marked T 23 S R 9 W S 23 B T.

Land, mountainous.

Soil, gravelly, 3rd rate.

Timber, Fir, Hemlock, Cedar, Alder.

Undergrowth of Salmonberries and Huckleberries.

Mountainous or heavily timbered land.

80.00 chains.

E. on blank line bet. secs. 24 and 25.

40.00 Set temporary  $\frac{1}{2}$  sec. cor.

September 10, 1898

79.74 Intersect E. bdy of Tp., 19 chs. S. of cor. of secs.

19 and 30, which is a cross, marked on a fir log, and  
 a fir post 4 ins. sq, 30 ins. high, marked and  
 witnessed as described by the surveyor general.

As this section does not close within limits, I remeasure  
 the Tp. line, which (see in Exterior lines, page <sup>2634</sup>~~15~~.)

At point of intersection, I set a Hemlock post, 3 ft. long,  
 4 ins. sq., 24 ins. in the ground for closing cor. of  
 secs. 24 and 25, marked C C T 23 S R 9 W on W.  
 S 24 on N.; and S 25 on S. faces, with 2 grooves on S.  
 and 4 grooves on N. faces, from which,

A Cedar, 12 ins. diam. bears N.50\*W., 31 lks. dist.  
 marked T 23 S R 9 W S 24 B T.

A Fir, 48 ins. diam., bears S.73 $\frac{1}{2}$ \*W., 58 lks. dist.,  
 marked T 23 S R 9 W S 25 B T