

County Surveyor's Record, Douglas County, Oregon

-49-

Subdivisions of T. 23 S., R. 9 W., W.M.
same Deputy and Contract.

CHAINS

- Descend slope of mountain, covered heavily with large fir, cedar and hemlock timber and with a dense undergrowth of vinemaple and huckleberries.
- 11.90 Descent becomes steeper.
- 35.50 A stream, 1 lk. wide, course SW. continue to descend
- 38.66 Set a cedar post, 3 ft long, 3 ins. sq, 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S 13 on N. face and 24 on S. face, from which
- A Fir, 36 ins. diam., bears N.65*W., 26 lks. dist., marked $\frac{1}{4}$ S 13 BT.
- A Cedar, 18 ins. diam. bears S.62 $\frac{1}{2}$ *W., 14 lks. dist. marked S 24 B T .
- This cor. stands 500 ft. below closing cor.,
Keep on descending.
- 47.00 Camp Creek, 30 lks. wide, course N., enter a bottom, covered with a dense undergrowth of salmon berries and vinemaple.
- September 13, 1898.
- 48.25 W.D. Owen's Trail to Lake Creek, bears N. and S.
- 58.00 Leave bottom, begin to ascend slope of mountain, covered heavily with timber.
- 67.00 The ascent becomes more gradual, a SE. slope.
- 73.00 A stream, 1 lk. wide, course SE.
Continue to ascend E. slope.
- 78.66 The cor. of secs. 13, 14, 23 and 24.
Land mountainous
Soil, loamy and gravelly; 2nd and 3rd rate.
Timber, fir, cedar, hemlock, maple, alder.
Undergrowth, dense, of salmonberries, huckleberries and vine-maple.
Mountains or heavily timbered land, or land covered by dense undergrowth.
- 78.66 and 20.10 chs.
-
- N.0*1'W. on random bet. secs. 13 and 14.
- 40.00 Set temp. $\frac{1}{4}$ sec. cor.