

County Surveyor's Record, Douglas County, Oregon

- 51 -

Subdivisions of T. 23 S., R. 9 W., W.M.

CHAINS

Timber, fir, hemlock, cedar, maple.

Dense undergrowth of small hemlocks, and salmonberries.

Mountainous or heavily timbered land or land covered by
a dense undergrowth.

115.42 chs.

September 15, 1898.

Cor. of Secs. 26, 27, 34 and 35.

S.0*2'E. on a random line bet. secs. 34 and 35.

40.00 Set temp. $\frac{1}{2}$ sec. cor.80.76 Intersect S. Edy. of Tp. 43 lks. E. of cor. of secs.
34 and 35. Thence I run

N.0*16'E. on true line bet. secs. 34 and 35.

Begin to ascend a SW. slope of mountain, covered, beside
timber, with a dense undergrowth of huckleberries,
hazel and vinemaples.

28.26 The ascent moderates.

40.76 Set a hemlock post, 3 ft. long, 3 ins. sq., 24 ins. in
the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. 34 on W. face
35 on E. face, from which,A Fir, 20 ins. diam., bears N.63*W., 33 lks. dist.,
marked $\frac{1}{4}$ S 35 B T.A Fir, 20 ins. diam., bears N.63*W., 20 lks. dist.,
marked $\frac{1}{4}$ S 34 B T.

Continue to ascend a SW. slope.

50.75 Top of ascent, 150 ft. above $\frac{1}{4}$ sec. cor., begin descent.71.90 A stream, 2 lks. wide, course E. along a benchland,
covered heavily with fir and hemlock timber.

80.76 The cor. of Secs. 26, 27, 34 and 35.

Land, mountainous.

Soil, gravelly; 3rd rate.

Timber, fir, hemlock, cedar, vinemaple, alder.

Dense undergrowth of huckleberries, hazel and vinemaple.

Mountainous or heavily timbered land, or land covered
by a dense undergrowth.

80.76 chs.