

## County Surveyor's Record, Douglas County, Oregon

- 63 -

Subdivisions of T. 23 S., R. 9 W., W.M.

## CHAINS

May 22, 1899.

W. on a random line bet. secs. 21 and 28.

40.00 Set temp.  $\frac{1}{4}$  sec. cor.

47.73 Intersect E. bdy. of sec. 20, 4.52 chs. N. of cor. of secs. 20, 21, 28 and 29 which is a cedar post, 5 ins. sq., 30 ins. above ground, marked and witnessed as described by the surveyor general. I destroyed all marks on cor. and witness trees, except those referring to sec. 20.

At the point of intersection, I set a fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for closing cor. of secs. 21 and 28, marked,

C C T 23 S R 9 W on E.; S 21 on N., and

S 28 on S. faces, with 4 grooves on E., and 2 grooves on S. faces, from which,

A Fir, 28 ins. diam., bears N.82\*E., 17 lks. dist. marked T 23 S R 9 W S 21 B T.

A Fir, 16 ins. diam., bears S.11\*E., 32 lks. dist., marked T 23 S R 9 W S 28 B T.

Thence I run,

East on true line bet. secs. 21 and 28. Ascend slope of mountain covered heavily with timber and dense undergrowth of huckleberries and vinemaple.

3.25. Top of spur, bears NW. and SE., begin descent.

7.73 A point, 80 ft. below top of spur, set a maple post, 3 ft long, 3 ins. sq., 24 ins. in the ground for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  S.21 on N. face and 28 on S. face from which,

A Fir, 28 ins. diam., bears S.30\*W., 18 lks. dist., marked  $\frac{1}{4}$  S 28 B T.

A Fir, 24 ins. diam., bears N.36\*W., 13 lks. dist., marked  $\frac{1}{4}$  S 21 B T.

Continue descending.