

County Surveyor's Record, Douglas County, Oregon

-70-

Subdivisions of R. 23 S., R. 9 W., W.M.

CHAINS

Begin descent of SW. slope.

79.56 The cor. of secs. 3, 4, 9 and 10, 250 ft. below top of ridge.

Land, mountainous.

Soil, gravelly, 3rd rate.

Timber, fir, hemlock, cedar, maple, alder.

Dense undergrowth of hazel, vinemaple, huckleberries.

Mountainous or heavily timbered and land covered with dense undergrowth.

79.56 chs.

May 28, 1899

W. on a random line bet. secs. 4 and 9

40.00 Set temp. $\frac{1}{4}$ sec. cor.

79.66 Intersected N. and S. line, 40 lks. N. of cor. of secs. 4, 5, 8 and 9. The post being gone, I re-establish same, by setting a hemlock post, 3 ft. long, 4 ins. sq. 24 ins. in the ground for cor. of secs. 4, 5, 8 and 9, marked and witnessed, as described by the surveyor general, thence I run

N.89°43'E. on true line bet. secs. 4 and 9.

Descend a mountainslope covered heavily with fir and hemlock timber.

1.25 A creek, 15 lks. wide, course N., slightly ascending N. slope.

30.20 A stream, 2 lks. wide, course N., along a bench covered heavily by timber.

32.15 A small pond is S. of line.

39.83 A Fir, 6 ins. in diam., for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S 4 on N. side, and 9 on S. side, from whichA Fir, 12 ins. diam., bears North 7 lks. dist., marked $\frac{1}{4}$ S 4 B T.A Fir, 6 ins. diam., bears S.28°E., 5 lks. dist., marked $\frac{1}{4}$ S. 9 B T.