

County Surveyor's Record, Douglas County, Oregon

-71-

Subdivisions of T. 23 S., R. 9 W., W.M.

CHAINS

Continue on a flat bench, covered with a dense undergrowth of vinemaple, small firs, and alders.

54.00 A creek, 10 lks. wide, bears NW., along a timber bench covered with a dense undergrowth.

64.10 Begin to ascend a S. slope of mountain

71.10 A stream, 3 lks. wide, course SW., begin ascent of W. mountain slope.

79.66 The cor. of secs. 3, 4, 9 and 10

Land mountainous

Soil, gravelly and clayey; 3rd rate.

Timber, fir, hemlock, cedar, alder, maple.

Dense undergrowth of vine maple, small firs and alders.

Mountainous or heavily timbered land or land covered by a dense undergrowth.

79.66 chs.

May 29, 1899.

N.0*2'W. on a random line bet. secs. 3 and 4

40.00 Set temp. $\frac{1}{4}$ sec. cor.

79.30 Intersected N. bdy. of Tp., 50 lks. E. of cor. of secs. 3, 4, 33 and 34. which is a fir post, 5 ins. sq., 3 ft. high, marked and witnessed as described by the surveyor general. Thence I run

S.0*23'E. on a true line bet. secs., 3 and 4.

Ascend a NW. slope of mountain covered heavily with timber.

12.30 Top of ridge, bears NE. and SW., begin steep descent.

28.90 A stream, 2 lks. wide, course SE., 300 ft. below top of ridge, begin steep descent of SE. slope.

33.40 A stream, 4 lks. wide, course NE., begin steep ascent.

39.30 A point, 120 ft. above last stream, I set a hemlock post 3 ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ sec. 4 on the W. face, 3 on the E. face, from which,

A Fir, 50 ins. diam., bears S.33*W., 13 lks. dist.,