

## County Surveyor's Record, Douglas County, Oregon

- 47 -

Subdivisions of T. 23 S., R. 9 W., W.M.

## CHAINS

marked  $\frac{1}{4}$  S 7 B T.

A Fir, 72 ins. diam., bears N.70\*W., 49 lks. dist.,

marked  $\frac{1}{4}$  S 7 B T.

Bearing of County road is N.75\*W. and S.75\*E.

7.75 Leave County road; ascend mountain.

13.25 County road, bears NW. and SE., on top of spur; begin to descend.

22.25 A stream, 3 lks. wide, course NW., 150 ft. below top of spur; begin to ascend.

36.55 Top of ridge, bears NW., and SE., 150 ft. above stream, enter an old burn, bears N. and S.

40.00 A point on S. slope of mountain, set a fir post, 3 ft. long, 3 ins. sq., 24 ins. in the ground for  $\frac{1}{4}$  sec. cor. of sec. 6, marked  $\frac{1}{4}$  S 6 on N. face, from which,  
A Fir, 60 ins. diam., bears N.2 $\frac{1}{2}$ \*W., 134 lks. dist.,  
marked  $\frac{1}{4}$  S 6 B T.A Fir, 30 ins. diam., bears S.50\*E., 61 lks. dist.,  
marked  $\frac{1}{4}$  S 6 B T.

47.25 Top of ridge, bears NE. and SW.

49.96 Intersect W. bdy of Tp. 38.58 chs. N.1\*W. of cor. of secs. 1, 6, 7 and 12, which is a laurel post 4 ins. sq., 39 ins. high, badly decayed, marked and witnessed as described by the surveyor general. The  $\frac{1}{4}$  sec. cor. near it's locus, I intersected the bdy. falls in a burn, and the post with it's bearing trees is burned up. I destroyed all marks referring to sec. 6, then at the point of intersection, I set an alder post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for closing cor. of secs. 6 and 7,

marked C C T 23 S R 9 W on E.; S 6 on N.;

S 7 on S. faces, with 1 groove on N. and 5 grooves on S. faces, from which,

A Fir, 6 ins. diam., bears N.38 $\frac{1}{2}$ \*E., 16 lks. dist.,  
marked T 23 S R 9 W S 6 B T.