

County Surveyor's Record, Douglas County, Oregon

South Boundary of T. 23 S., R. 10 W.

CHAINS

A fir, 24 ins. diam., bears S.20*W., 76 lks. dist.

A fir, 24 ins. diam., bears N.52*W., 78 lks. dist.

Land, broken; rocky, 3rd rate.

Timber chiefly fir, hemlock, maple and cedar.

Underbrush same; vine maple, huckleberry and salmonberry brush.

South 89*49'W, on South bdy. of Sec. 35.

Va. 19* East.

15.50 Top of spur, course SE.

19.00 Spring, course E.

40.00 Marked a fir, 5 ins. diam., for the $\frac{1}{4}$ sec. cor. between secs. 2 & 35, from which

A fir, 16 ins. diam., bears N.50*E., 11 lks. dist.

A fir, 36 ins. diam., bears South, 27 lks. dist.

56.25 A creek, 10 lks. wide, course SE.

61.00 A creek, 3 lks. wide, course N.75*E.

80.00 Set a yew post 5 ft. long, 5 in. diam., 20 ins. in the ground for the corner to secs. 2, 3, 34 & 35, from which

A fir, 36 ins. diam., bears N.15*E., 37 lks. dist.

A fir, 20 ins. diam., bears S.58*E., 17 lks. dist.

A fir, 20 ins. diam., bears S.61*W., 24 lks. dist.

A fir, 30 ins. diam., bears N.3*W., 42 lks. dist.

Description of land and timber same as last line.

May 23rd, 1879.

South 89*49' West on South bdy. of sec. 34.

Va. 19*E.

27.00 Creek, 2 lks. wide, course S.

34.50 Creek, 2 lks. wide, course SE.

40.00 Set a maple post 5 ft. long, 5 ins. in diam., 20 ins. in ground for the $\frac{1}{4}$ sec. cor. between secs. 3 & 34, from which