

Subdivisional Lines of T. 23 S., R. 10 W.

CHAINS
79.90

To sec. cor.

Land, 3rd rate on mountain, 1st rate in bottom.

Timber same on hills as last line. Myrtle, maple, ash, crabapple and alder in bottom.

North between secs. 11 and 12.

Va. 19*East.

23.00 A spring branch, course E.

40.00 Set a laurel post, 5 ft. long, 5 ins. in diam., 20 ins. in ground for the $\frac{1}{4}$ sec. cor. between secs. 11 and 12, from which

A fir, 8 ins. diam., bears S.25*E., 33 lks. dist.

A fir, 10 ins. diam., bears S.50*W., 25 lks. dist.

45.00 Intersect lake at mouth of small creek, 2 lks wide. Set Meander post, marked an alder, 5 ins. diam., from which

An alder, 10 ins. diam., bears S.5*E., 4 lks. dist.

An alder, 8 ins. diam., bears S.5*W., 5 lks. dist.

May 30th, 1879.

Base West 200 lks.

Angle opposite 9* Nat. Cotangent 6.3137575

Multiply by base 2.00

12.627503000.

57.63 Across lake. Marked a laurel, 8 ins. diam., for Meander post, from which

A fir, 20 ins. diam., bears N.20*E., 23 lks. dist.

A fir, 16 ins. diam., bears N.30*W., 18 lks. dist.

68.75 Intersect Lake. Marked a yew, 24 ins. diam., for the Meander cor. & witness to corner to secs. 1, 2, 11 and 12. No witness trees convenient. Sec. cor. in lake.

Land, broken, 3rd rate.

Timber chiefly dead fir.

Undergrowth same.