

Subdivisional Lines of T. 23 S., R. 10 W.

CHAINS 65.00 68.75 80.40	Steep descent. To Meander Post on East Boundary of Lake Cor. in lake. Land, broken, mountainous, 3rd rate. Timber, old burn nearly all destroyed. Underbrush, dense fir, mountain balm, laurel etc.
40.00 122.15 24.00 69.00 82.15 83.00 92.25 122.15	North on random line between secs. 1 and 2. <p style="text-align: right;">Va. 19*E.</p> Set temp. $\frac{1}{4}$ sec. cor. Intersect at cor. to sec. 1 and 2 on North Boundary. South on true line. <p style="text-align: right;">May 31st, 1879.</p> Mill Creek, 150 lks. wide, course NE. Top of spur, course West. Set a fir post, 5 ft. long 4 ins. in diam., 20 ins. in ground for the $\frac{1}{4}$ sec. cor. between secs. 1 & 2, from which <p style="margin-left: 40px;">A fir, 24 ins. diam., bears N.33*E., 56 lks. dist.</p> <p style="margin-left: 40px;">A laurel, 6 ins. diam., bears West, 20 lks. dist.</p> Perpendicular bluff, 75 ft. high. Intersect lake marked an ash, 4 ins. diam., for the Meander cor. between secs. 1 & 2, from which <p style="margin-left: 40px;">A fir, 18 ins. diam., bears N.20*E., 70 lks. dist.</p> <p style="margin-left: 40px;">A fir, 24 ins. diam., bears N.45*W., 60 lks. dist.</p> To sec. cor. Land mountainous, rocky, broken, 3rd rate. Timber and underbrush similar to former line. <p style="text-align: right;">June 1st, 1879.</p>
Beginning at the established cor. to secs. 34 & 35, South boundary of Tp. North on true line between secs. 34 & 35. <p style="text-align: right;">Va. 19*East.</p>	