

County Surveyor's Record, Douglas County, Oregon

Subdivisional Lines of T. 23 S., R. 10 W.

CHAINS

- A fir, 10 ins. diam., bears N.23*E., 95 lks. dist.
- A fir, 50 ins. diam., bears S.45*E., 72 lks. dist.
- A fir, 20 ins. diam., bears S.75*W., 54 lks. dist.
- A fir, 8 ins. diam., bears N.15*W., 131 lks. dist.

Land description same as preceeding line.
 Timber & underbrush same.

East on random line between secs. 11 & 14.

Va. 19*E.

- 40.00 Set temp. 1/4 sec. cor.
- 80.60 Intersect line 62 lks. North of cor.
North 89*33'West on true line.
- 10.00 Begin steep ascent.
- 40.30 Set yew post 4 ft. long, 5 ins. diam., 20 ins. in
ground for the 1/4 sec. cor. between secs. 11 & 14, from
which
 - A fir, 24 ins. diam., bears N.40*E., 47 lks. dist.
 - A fir, 36 ins. diam., bears S.50*W., 15 lks. dist.
- 51.75 A creek, 1 lk. wide, course NW.
- 67.50 A creek, 20 lks. wide, course NE.
- 80.60 To sec. corner.

Land rocky, broken, 3rd rate.
 Timber principally destroyed by fires.
 Undergrowth chiefly fir, hemlock & mountain balm.
 North is too rocky, broken and barren to be fit or
 practable to be surveyed.

June 4th 1879.

Meanders of Loon Lake in Secs. 1, 2, 11 & 12.

In sec. 12.

Beginning at the Meander Post on South side of lake
 between secs. 11 and 12. I run, Va. 19*

- S.53*E. 13.50
- East 35.00
- S.40*W. 3.50 Marshy shores.