

Resurvey of South Boundary of T. 23 S., R. 10 W.

CHAINS

A fir, 36 ins. diam., bears S.57*W., 70 lks. dist.

Marked T 24 S R 10 W S 1 B T

A fir, 36 ins. diam., bears N.25*W., 12 lks. dist.

Marked T 23 S R 10 W S 36 B T

Land, mountainous, 75.71 chs.

Soil, 2nd and 3rd rate

Timber, fir, hemlock, maple, chinquapin, alder, madrona,
chitten-wood and myrtle

Dense undergrowth, vine maple, rhododendron, huckle-berry,
thimble-berry, salmon-berry, salal-berry, ocean spray
and Oregon grape, 75.71 chs.

Note: The true course of this line from the cor. to Tps.
23 and 24 S., Rs. 9 and 10 W. to the cor. to secs. 35
and 36. Tp. 23 S. is S.88*26'W. and the whole distance
is 75.71 chs.

Retracement of the South Bdy. of Sec. 34, T. 23 S.,
R. 10 W., as surveyed by Levi C. Walker, Deputy Surveyor
Under Special Instructions dated August 23, 1905,
Independent of, but in connection with his contract
No. 763, dated June 20, 1905

At the closing cor. of secs. 33 and 34, T. 23 S., R. 10 W.
heretofore described

Thence I run

N.89*49'E., on a blank line along the S. bdy. of sec. 34

Over mountainous land through heavy timber and dense under-
growth.

41.20

My line falls 11 lks. S. of the $\frac{1}{4}$ sec. cor. which is an
unmarked post, firmly set and witnessed as described by
the Surveyor General

The true bearing of this portion of the line is therefore
N.89*49'E.

Thence from the $\frac{1}{4}$ sec. cor.

I run

N.89*49'E., on a blank line along the S. bdy. of sec. 34

13.00

Branch, 3 lks. wide; course SE.