

County Surveyor's Record, Douglas County, Oregon

South Boundary of T 24 S R 1 W

CHAINS	
	<p>Land, mountainous</p> <p>Soil, 3rd rate and 4th rate</p> <p>Timber, fir, hemlock, cedar, pine, yew, chincapin, dog-wood, maple, and alder.</p> <p>Dense undergrowth of rhododendron, vine-maple, hemlock, fir, chincapin, mountain-balm, hazel, and salal-berry.</p> <p>Mountainous land, or covered with dense undergrowth,</p> <p>80.00 chs.</p> <p style="text-align: right;">July 19, 1896</p>
	<p>East on true line, along S bdy. of sec. 33. Mag Decl. 20*E Ascend</p>
13.07	<p>Top of ridge, bears N and S about 50 ft. above sec. cor. Begin descent</p>
30.10	<p>Dry bed of creek, course S about 75 ft. below ridge.</p>
36.98	<p>Creek, 3 lks. wide, course S., about 100 ft. below ridge Begin ascent</p>
40.00	<p>Set a hemlock post 4 ft. long 4 ins. sq. 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face, from which</p> <p style="padding-left: 40px;">A yew, 12 ins. diam., bears S.82*E., 27 lks. dist. Marked $\frac{1}{4}$ S B T</p> <p style="padding-left: 40px;">A hemlock, 36 ins. diam., bears N.55*W., 17 lks. dist. Marked $\frac{1}{4}$ S B T</p> <p>This cor. is on a hillside, sloping W about 25 ft. above creek.</p>
42.00	<p>A fir, 48 ins. diam., on line, I mark with 2 notches on E and W sides</p>
54.75	<p>Top of ridge, bears N.80*W., and S.80*E., about 50 ft. above $\frac{1}{4}$ sec. cor. Begin descent</p>
62.72	<p>Creek, 1 lk. wide, course NW about 100 ft. below ridge Begin ascent</p>
71.78	<p>Top of spur, sloping N about 25 ft. above creek. Begin descent</p>