

County Surveyor's Record, Douglas County, Oregon

Retracement of the East Bdy. of T. 24 S., R. 2 W.

CHAINS

The instrument was adjusted July 11 and 12, 1896, preliminary to the survey of Willemette Meridian, through Tps. 24 and 25 S., bet. Rs. 1 E and 1 W

Preliminary to the survey of the subdivisional lines of T 24 S, R 1 W, from the cor. of Ts. 24 and 25, S. R. 2 W., which I reestablished on the W Bdy. of T. 24 S., R. 1 W., July 18, 1896, I run

North, on a blank line, bet. secs. 31 and 36

36.88 To a point, 39 lks. E of $\frac{1}{4}$ sec. cor.

This $\frac{1}{4}$ sec. cor. I find in a delapidated condition; B T in sec. 31 blown down; no trace of post to be found. I reestablish as follows; At the exact point for the $\frac{1}{4}$ sec. cor., determined by the old B T and data furnished by the surveyor general

Set a basalt stone, 10x10x8 ins., 7 ins. in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on W face, from which

A fir, 24 ins. diam., bears N.29*E., 30 lks. dist.

Marked $\frac{1}{4}$ S B T

A fir, 6 ins. diam., bears S.73*W., 16 lks. dist.

Marked $\frac{1}{4}$ S B T

Therefore, this line bears N.36'W and is 36.88 chs. in length.

From this $\frac{1}{4}$ sec. cor., I run North, on blank line, bet. secs. 36 and 31

35.06 Intersect E and W line, 575 lks. W of cor. of secs. 30, 31, 36 and 25, which is a cedar post, 2 ft. above ground, marked as, but not witnessed as, described by the surveyor general

This cor. not being correct in position, I reestablish, as follows.

Set a cedar post, 4 ft. long, 4 ins. sq. 24 ins. in the ground, for cor. of secs. 25 and 36, marked T 24 S S 36 on SW, and R 2 W S 25 on NW, faces; with 1 notch on S and 15 notches on N edges; from which