

County Surveyor's Record, Douglas County, Oregon

East Boundary of T. 24 S., R. 2 W.

CHAINS	<p>Land, mountainous.</p> <p>Soil, 3rd rate.</p> <p>Densely covered with forest of fir, pine, hemlock, maple, laurel and dogwood.</p> <p>Thick undergrowth of laurel, hazel, vine maple & sallow.</p> <p style="text-align: right;">May 28, 1883.</p>
	<p>North, bet. secs. 13 & 18.</p> <p style="text-align: right;">Var. 19$\frac{1}{2}$*E.</p>
	<p>Through heavy timber.</p>
13.40	<p>A cedar, 24 ins. diam.</p>
17.50	<p>Rock Creek, 20 lks. wide, course S.60*E.</p>
23.10	<p>A fir, 36 ins. diam.</p>
39.16	<p>A fir, 20 ins. diam.</p>
40.00	<p>Set cedar post, 3 ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on W. face, from which</p> <p style="padding-left: 40px;">A chinquapin, 16 ins. diam., bears S.61*E. 14 lks. dist. marked $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A laurel, 5 ins. diam., bears N.55*W. 6 lks. dist. marked $\frac{1}{4}$ S B T.</p>
41.10	<p>Descend rocky bluff.</p>
47.30	<p>A fir, 40 ins. diam.</p>
80.00	<p>Set cedar post, 4 ft. long, 4 ins. sq., 24 ins. in the ground for cor. to secs. 7, 12, 13 & 18. marked T 24 S S 7 on NE., R 1 W S 18 on SE., R 2 W S 13 on SW., and S 12 on NW. faces, with 2 notches on N. and 4 notches on S. edges, from which</p> <p style="padding-left: 40px;">A fir, 24 ins. diam., bears N.75*E. 26 lks. dist. marked T 24 S R 1 W S 7 B T.</p> <p style="padding-left: 40px;">A fir, 30 ins. diam., bears S.81*E. 30 lks. dist. marked T 24 S R 1 W S 18 B T.</p> <p style="padding-left: 40px;">A hemlock, 32 ins. diam., bears S.75*W. 46 lks. dist. marked T 24 S R 2 W S 13 B T.</p>