

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 24 S., R. 2 W.

CHAINS	dendron, 80.00 chs. Soil, sandy and rocky, 3rd and 4th rate.
	East, on a random line bet. secs. 14 and 23. Var. 20*E.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
79.80	Intersect N. and S. line 40 lks. S. of the cor. to secs. 13, 14, 23 and 24. Thence I run S.89*43'W. on a true line bet. secs. 14 and 23. Var. 20*E.
0.10	Through heavy timber, descend about 300 ft. to Cedar, 40 ins. diam.
2.00	Creek, 1 lk. wide, course NW.
9.75	Same creek, course SW.
24.75	Creek, 1 lk. wide, course S.
31.75	Creek, 5 lks. wide, course S. and ascend about 150 ft.
39.90	Set a post 3 ft. long and 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on N. face, from which A hemlock, 5 ins. diam., bears N.35*E. 32 lks. dist. marked $\frac{1}{4}$ S B T. A hemlock, 24 ins. diam., bears S.17*W. 40 lks. dist. marked $\frac{1}{4}$ S B T.
44.00	Top of spur, course S. and descend about 350 ft. to
77.00	Creek, 2 lks. wide, course SW. and ascend about 50 ft. to
79.80	The cor. to secs. 14, 15, 22 and 23. Land, mountainous and heavily timbered with fir and hem- lock. With dense undergrowth of hemlock and rhododendron 79.80 chs. Soil, sandy and rocky, 3rd and 4th rate. Sept. 12, 1894.
	N.0*2'W. bet. secs. 14 and 15. Var. 20*E.