

## County Surveyor's Record, Douglas County, Oregon

67  
Subdivisions of T. 24 S., R. 2 W.

|        |   |
|--------|---|
| CHAINS | <p>A cedar, 7 ins. diam., bears S.84*E. 37 lks. dist.<br/>marked <math>\frac{1}{4}</math> S B T.</p> <p>A hemlock, 9 ins. diam., bears N.52*W. 26 lks. dist.<br/>marked <math>\frac{1}{4}</math> S B T.</p>   |
| 45.00  | Creek, 3 lks. wide, course SW. and ascend about 150 ft. to  |
| 77.00  | Top of bench, course E. & W. Thence over bench to   |
| 80.00  | Set a post 4 ft. long and 4 ins. sq., 24 ins. in the<br>ground for cor. to secs. 5, 6, 7 and 8 marked T 24<br>S S 5 on NE., R 2 W S 8 on SE., S 7 on SW. and S 6 on<br>NW. faces, with 5 notches on S. and E. edges, from<br>which  |
|        | <p>A fir, 10 ins. diam., bears N.27*30'E. 53 lks. dist.<br/>marked T 24 S R 2 W S 5 B T.</p> <p>A hemlock, 20 ins. diam., bears S.66*E. 46 lks. dist.<br/>marked T 24 S R 2 W S 8 B T.</p> <p>A fir, 30 ins. diam., bears S.39*W. 42 lks. dist.<br/>marked T 24 S R 2 W S 7 B T.</p> <p>A fir, 36 ins. diam., bears N.19*30'W. 53 lks. dist.<br/>marked T 24 S R 2 W S 6 B T.</p> |
|        | Land, mountainous and heavily timbered with fir, hem-<br>lock and scattering cedar.   |
|        | With a dense undergrowth of vine maple and rhododendron,<br>80.00 chs.  |
|        | Soil, sandy and rocky, 3rd and 4th rate.  |
|        | Sept. 24, 1894.   |
| 40.00  | N.89*53'E. on a random line bet. secs. 5 and 8.<br>Var. 20*E.<br>Temp. $\frac{1}{4}$ sec. corner.   |
| 79.60  | Intersect N. and S. line 31 lks. S. of the cor. to secs.<br>4, 5, 8 and 9.<br>Thence I run<br>S.89*39'W. on a true line bet. secs. 5 and 8.<br>Var. 21*30'E.  |
|        | Through heavy timber, descend about 300 ft. to  |