

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 2 W.

CHAINS

41.75

Set a post 3 ft. long and 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on N. face, from which

A vine maple, 6 ins. diam., bears N.28*W. 13 lks. dist., marked $\frac{1}{4}$ S B T.

A hemlock, 16 ins. diam., bears N.12*E. 24 lks. dist., marked $\frac{1}{4}$ S B T.

42.75

Creek, 3 lks. wide, course NW. and ascend about 400 ft.

53.75

Creek, 1 lk. wide, course NE.

81.75

The cor. to secs. 5, 6, 7 & 8.

Land, mountainous and heavily timbered with fir and hemlock.

With dense undergrowth of vine maple and rhododendron, 81.75 chs.

Soil, sandy and rocky, 3rd and 4th rate.

Sept. 25, 1894.

By reference to the notes of the survey of the south boundary of T. 23 S., R. 2 W. it will be seen that the north boundary of sec. 6 in Tp. 24 S., R. 2 W. is 68.15 chs. in length, and that a closing corner was established at a point 10.75 chs. north of the SE. cor. of Tp. 23 S., R. 3 W.

The cor. to Tp. 24 S., Rs. 2 and 3 W. which was established when the range line between Tp. 24 S., Rs. 2 & 3 W. was run, found to be wrongly located. Therefore I destroyed it, and in order to correctly show the boundaries of Sec. 6, T. 24 S., R. 2 W., I go to the cor. to secs. 1, 6, 7 & 12, T. 24 S., Rs. 2 & 3 W., which is a post 4 ft. long and 4 ins. sq., firmly set in the ground, marked T 24 S S 6 on NE., R 2 W S 7 on SE., R 3 W S 12 on SW. and S 1 on NW. faces, with 1 notch on N. and 5 notches on S. faces, from which

A maple, 7 ins. diam., bears N.71*E. 20 lks. dist. marked T 24 S R 2 W S 6 B T.