

County Surveyor's Record, Douglas County, Oregon

Subdivisions of ⁷²T. 24 S., R. 2 W.

CHAINS

And at the point of intersection set a post $4\frac{1}{2}$ ft. long and 4 ins. sq., 24 ins. in the ground for closing cor. to secs. 1 and 6, T 24 S., Rs. 2 & 3 W., marked C C T 24 S on S., R 2 W S 6 on E. and R 3 W S 1 on W. faces, 6 notches on S. E. and W. faces, from which

A fir, 60 ins. diam., bears S.70°E. 56 lks. dist. marked T 24 S R 2 W S 6 B T.

A yew, 18 ins. diam., bears S.24°W. 59 lks. dist. marked T 24 S R 3 W S 1 B T.

A fir, 60 ins. diam., bears N.37°W. 32 lks. dist. marked C C T 24 S Rs. 2 and 3 W B T.

Land, mountainous and heavily timbered with fir and hemlock, with dense undergrowth of vine maple, & hemlock, 71.15 chs.

Soil, sandy & rocky, 3rd and 4th rate.

Sept. 26, 1894.

50 miles 72 chains 91 links of the foregoing survey pass over lands that are mountainous or heavily timbered, or covered with dense undergrowth.

General Description

This Tp. is mountainous and broken, and is chiefly valuable for its timber, it being covered with a heavy growth of fir, hemlock and scattering cedar.

The soil is sandy and rocky and is unfit for agricultural purposes.

The entire Tp. is well watered with numerous small streams of pure clear water.