

County Surveyor's Record, Douglas County, Oregon

2

South Boundary of T. 24 S., R. 3 W.

CHAINS		
43.75	Spring branch 1 lk. wide, course N.	+160
	August 8, 1871	
63.00	Top of spur, course N. Old crater 100 lks. wide	+500
80.00	Set post cor. to secs. 5, 6, 31 and 32 from which	+375
	A hemlock, 5 ins. diam., bears N.52*E. Dist. 5 lks.	
	A hemlock, 6 ins. diam., bears S.70*E. Dist. 8 lks.	
	A hemlock, 6 ins. diam., bears S.81*W. Dist. 9 lks.	
	A hemlock, 5 ins. diam., bears N.52*W. Dist. 10 lks.	
	Land uneven	
	Good soil along creek, fit for cultivation	
	Timber good, various kinds of fir and cedar on the hills.	
	Maple and ash on the bottoms.	
	East on true line along the S. boundary of Sec. 32	
	Var. 19*30'E.	
9.50	South fork of Calapooia Creek 75 lks. wide, course NW.	-300
25.00	Begin ascent	000
32.50	Small stream 1 lk. wide, course SW.	- 25
40.00	Set $\frac{1}{4}$ sec. post from which	+ 25
	A fir, 16 ins. diam., bears N.28*W. Dist. 12 lks.	
	A maple, 9 ins. diam., bears S.60*E. Dist. 24 lks.	
80.00	Set post cor. to secs. 4, 5, 32 & 33 from which	+500
	A cedar, 16 ins. diam., bears N.60*E. Dist. 13 lks.	
	A cedar, 24 ins. diam., bears S.60*E. Dist. 9 lks.	
	A cedar, 12 ins. diam., bears S.80*W. Dist. 17 lks.	
	A fir, 16 ins. diam., bears N.75*W. Dist. 19 lks.	
	Land good for cultivation on creek bottom. Balance,	
	rough, mountainous. 2nd rate.	
	Timber good. Firs, cedar, ash and maple the principal	
	kinds.	
	East, on a true line along the S. Boundary of Sec. 33	
	Var. 19*E.	
5.00	A good spring, course S.	
35.00	Begin steep ascent	