

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 3 W.

CHAINS		
40.20	Set $\frac{1}{4}$ sec. post from which A hemlock, 20 ins. diam., bears N. 8 lks. A maple, 5 ins. diam., bears S.10*W. 17 lks.	+400
48.90	A perpendicular bluff 20 ft. high	-100
50.90	Enter valley	-250
70.40	Left branch of Calapooia creek 35 lks. wide, course SW.	-450
73.90	Across island to right branch of creek 50 lks.	-450
75.40	Begin ascent	-450
80.40	The cor. to secs. 15, 16, 21 and 22 Land West part 1st rate. East part 2nd rate. Timber good. Fir, cedar, hemlock, maple, ash and yew. Underbrush same with vine maple, hazel and mountain laurel. Salmon, and some other briars along the creek.	-200
	South, between secs. 21 & 22 Var. 19*E.	
3.00	Right branch of Calapooia Creek 75 lks. wide, course W.	-250
7.00	Left branch of same 50 lks. wide, course W.	-250
8.00	Begin ascent	-250
40.00	Set $\frac{1}{4}$ sec. post from which A fir, 6 ins. diam., bears N.25*E. dist. 11 lks. A fir, 5 ins. diam., bears S.60*W. dist. 10 lks. Land 1st and 2nd rate mountain land. Mountain steep and high to the South Timber 2nd rate Underbrush very thick. Mostly young fir and hazel. August 16, 1871	+800
	West, on a true line between secs. 16 and 21. Var. 19*E.	
19.50	A creek 2 lks. wide, course S.	-100
40.00	Set $\frac{1}{4}$ sec. post from which A fir, 10 ins. diam., bears N.5*E. dist. 40 lks. A fir, 7 ins. diam., bears S.28*E. dist. 40 lks.	