

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 24 S., R. 3 W.

CHAINS	East, on a true line between secs. 21 and 28. Var. 19*45'E.	
20.00	A spring branch, course S.80*W.	+100
40.00	Set $\frac{1}{4}$ sec. post from which A maple, 14 ins. diam., bears N.10*W. dist. 11 lks. A fir, 10 ins. diam., bears S.68*E. dist. 38 lks. Land 2nd rate. Gradual slope to the West. Timber, 2nd rate. Fir, cedar, maple and yew. Underbrush same and vine maple.	+600
	South, between Secs. 28 and 29 Var. 19*45'E.	
14.75	A creek 3 lks. wide, course W.	-100
32.00	Begin ascent	
40.00	Set $\frac{1}{4}$ sec. post from which A cedar, 10 ins. diam., bears N.80*E. dist. 5 lks. A fir, 14 ins. diam., bears N.35*W. dist. 31 lks.	+600
41.00	Top of spur, course W.	+650
45.00	A spring branch, course W.	+250
80.00	Set post cor. to secs. 28, 29, 32 and 33 from which A fir, 10 ins. diam., bears N.55*E. dist. 13 lks. A fir, 7 ins. diam., bears S.35*E. dist. 22 lks. A fir, 11 ins. diam., bears S.22*W. dist. 12 lks. A fir, 6 ins. diam., bears N.76*W. dist. 14 lks. Land 2nd rate. South part hilly. Timber good. Principally fir, cedar, maple and yew. Underbrush same August 17, 1871	+750
	North, between secs. 31 and 32 Var. 19*30'E.	
1.25	A perpendicular precipice 15 ft.	-100
5.75	A creek 75 lks. wide, course NW.	-300
12.50	Begin ascent	-300
29.50	Top of spur, course W.	