

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 3 W.

CHAINS		
	Land broken, 2nd rate.	
	Timber young and nearly all destroyed by fires. South part of line very brushy. A specie of spice.	
	East, on a random line between secs. 20 and 29.	
	Var. 20*E.	
40.00	Set temp. $\frac{1}{2}$ sec. post	
79.04	Intersect line 98 lks. N. of post cor. to secs. 20, 21, 28 and 29.	
	North 89*18' West on a true line between secs. 20 and 29.	
6.50	A creek 3 lks. wide, course N.85*W.	-100
27.50	Calapoca Creek 150 lks. wide, course SW.	375
39.02	Set $\frac{1}{2}$ sec. post from which	300
	A cedar, 8 ins. diam., bears N.20*W. 8 lks.	
	A dogwood, 5 ins. diam., bears S. 9 lks.	
51.54	A creek, 7 lks. wide, course S.	200
78.54	A creek, 5 lks. wide, course N.80*E.	150
79.04	The cor. to secs. 19, 20, 29 and 30	150
	Land, 1st rate. Bottom land mostly.	
	Timber, 1st rate. Fir, hemlock, cedar, yew, maple and ash.	
	But little underbrush. Vine maple.	
	West, on a random line between secs. 19 and 30.	
	Var. 20*E.	
40.00	Set temp. $\frac{1}{2}$ sec. post.	
80.00	Could find no corner. Ascertained that the Tp. line was not extended farther North than along East boundary of Sec. 36. Set temp. post and threw up rock mound.	
	Thence	
	East, on a true line between secs. 19 and 30.	
4.00	Leave burned woods	
21.00	Top of ridge, course N. & S.	+600
32.00	Begin descent	+600
40.00	Set $\frac{1}{2}$ sec. post from which	+400