

Subdivisions of T. 24 S., R. 3 W.

| | | |
|--------|---|-------|
| CHAINS | <p>hemlock, cedar, maple, alder, laurel, chinquapin, yew & chittim.</p> <p>Thick undergrowth of sallal, vine maple, hazel, fir, manzanita, thimble, huckle, salmon & elder berry & arrow wood.</p> <p style="text-align: right;">May 24, 1883.</p> | |
| | <p>North, on random line between Secs. 2 & 3.</p> <p style="text-align: right;">Var. $21\frac{1}{4}^{\circ}$E.</p> <p>Through timber.</p> <p>Descend.</p> | |
| 30.00 | A canyon, course E. & W. | -1000 |
| 32.15 | A fir, 36 ins. diam. | |
| 38.20 | A hemlock, 20 ins. diam. | |
| 40.00 | Set temp. $\frac{1}{4}$ sec. cor. | |
| 47.35 | A fir, 50 ins. diam. | |
| 68.50 | A ridge, course E. & W. | +1000 |
| 72.30 | A brook, 1 lk. wide, course W. | |
| 75.13 | A hemlock, 40 ins. diam. | |
| 79.30 | <p>Intersect the North bdy. of Tp. 107 lks. E. of cor. to secs. 2 & 3, 34 & 35, which is a cedar post, 4 ins. sq., firmly set in the ground marked T 23 S R 3 W S 35 on NE., T 24 S R 3 W S 2 on SE., T 24 S R 3 W S 3 on SW., and T 23 S R 3 W S 34 on NW. faces, with 2 notches on E. and 4 notches on W. edges, from which</p> <p style="padding-left: 40px;">A maple, 6 ins. diam., bears S.40*W. 49 lks. dist. marked T 24 S R 3 W S 3 B T.</p> <p style="padding-left: 40px;">A fir, 36 ins. diam., bears N.15*E. 45 lks. dist. marked T 23 S R 3 W S 35 B T.</p> <p style="padding-left: 40px;">A fir, 36 ins. diam., bears S.1*E. 19 lks. dist. marked T 24 S R 3 W S 2 B T.</p> <p style="padding-left: 40px;">A fir, 20 ins. diam., bears N.30*W. 44 lks. dist. marked T 23 S R 3 W S 34 B T.</p> <p>Thence I run</p> <p>S.46'E. on a true line bet. secs. 2 & 3 with same var.</p> | |