

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 24 S., R. 3 W.

CHAINS  
80.95

The cor. to secs. 4, 5, 8 &amp; 9.

Land, mountainous and densely covered with forest.

Soil, 3rd rate.

Timber, fir, cedar, hemlock, maple and alder.

Thick undergrowth of sallal, vine maple, hazel, fir, manzanita and salmon berry.

June 1, 1883.

The cor. to secs. 19, 20, 29 and 30 having been destroyed by fire, I run north bet. secs. 29 and 30 following the old blazed line and at 80.00 chs. from the cor. to secs. 29, 30, 31 and 32, marked a hemlock, 24 ins. diam., for cor. to secs. 19, 20, 29 and 30, T 24 S S 20 on NE., R 3 W S 29 on SE., S 30 on SW. and S 19 on NW. faces, from which

A hemlock, 12 ins. diam., bears N.69\*E. 36 lks. dist.  
marked T 24 S R 3 W S 20 B T.

A hemlock, 4 ins. diam., bears S.44\*E. 23 lks. dist.  
marked T 24 S R 3 W S 29 B T.

A hemlock, 14 ins. diam., bears S.46\*W. 45 lks. dist.  
marked T 24 S R 3 W S 30 B T.

A hemlock, 14 ins. diam., bears N.59\*W. 28 lks. dist.  
marked T 24 S R 3 W S 19 B T.

Thence I run

North, between Secs. 19 &amp; 20.

Var. 21 $\frac{1}{2}$ \*E.

Descend through timber.

15.25 A fir, 40 ins. diam.

18.25 A brook, 3 lks. wide, course E.

35.00 A ridge, course NW. &amp; SE.

40.00 A hemlock post, 3 ft. long, 3 ins. sq., 24 ins. in the ground for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  S. on W. face, from which

A fir, 24 ins. diam., bears N.41\*W. 5 lks. dist.  
marked  $\frac{1}{4}$  S B T.

\*1000