

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 3 W.

CHAINS		
	A cedar, 16 ins. diam., bears S.59*W. 54 lks. dist. marked $\frac{1}{4}$ S B T.	
48.20	A brook, 2 lks. wide, course SE.	
62.82	A fir, 50 ins. diam.	
66.55	A hemlock, 36 ins. diam.	
70.50	A ridge, course N.20*W. & S.20*E.	+1000
80.00	<p>Set cedar post 4 ft. long, 4 ins. sq., 24 ins. in the ground for cor. to secs. 17, 20, 18 & 19 marked T 24 S S 17 on NE., R 3 W S 20 on SE., S 19 on SW. & S 18 on NW. faces, with 3 notches on S. & 5 notches on E. edges, from which</p> <p>A fir, 50 ins. diam., bears N.31*E. 45 lks. dist. marked T 24 S R 3 W S 17 B T.</p> <p>A hemlock, 5 ins. diam., bears S.14*E. 38 lks. dist. marked T 24 S R 3 W S 20 B T.</p> <p>A maple, 7 ins. diam., bears S.71*W. 23 lks. dist. marked T 24 S R 3 W S 19 B T.</p> <p>A hemlock, 18 ins. diam., bears N.30*W. 18 lks. dist. marked T 24 S R 3 W S 18 B T.</p>	
	<p>Land, mountainous.</p> <p>Soil, 3rd rate.</p> <p>Densely covered with forests of fir, hemlock, cedar, maple, alder, laurel, chinquapin, yew & chittim.</p> <p>Thick undergrowth of sallah, vine maple, hazel, fir, manzanita, thimble, huckle, salmon & elder berry & arrow wood.</p>	
	<p>East, on random line between secs. 17 & 20.</p> <p style="text-align: right;">Var. 21 $\frac{3}{4}$*E.</p>	
	Through timber.	
21.32	A fir, 50 ins. diam.	
26.76	A fir, 36 ins. diam.	
30.10	A brook, 3 lks. wide, course SE.	
32.70	A fir, 40 ins. diam.	
36.50	A ridge, course N. & S.	+800
40.00	Set temp. $\frac{1}{4}$ sec. cor.	