

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 24 S., R. 3 W.

CHAINS	<p>Land, mountainous.</p> <p>Soil, 3rd rate.</p> <p>Densely covered with forests of red, yellow &amp; white fir, hemlock, cedar, maple, alder, laurel, chinquapin, yew &amp; chittim.</p> <p>Thick undergrowth of sallal, vine maple, hazel, fir, manzanita, thimble, huckle, salmon &amp; elder berry &amp; arrow wood.</p> <p style="text-align: right;">June 3, 1883.</p>	
	<p>East, on random line between Secs. 8 &amp; 17.</p> <p style="text-align: right;">Var. <math>21\frac{1}{8}^*E</math>.</p>	
	<p>Through timber.</p>	
16.75	A hemlock, 30 ins. diam.	
38.00	A canyon, course N. & S.	-1000
40.00	Set temp. $\frac{1}{4}$ sec. cor.	
52.10	A hemlock, 20 ins. diam.	
60.50	A ridge, course N. & S.	+800
60.75	A chinquapin, 20 ins. diam.	
71.15	A brook, 2 lks. wide, course S.	
80.34	<p>Intersect the N. &amp; S. line 10 lks. S. of cor. to secs. 8, 9, 16 &amp; 17.</p> <p>Thence I run</p> <p>S. <math>89^*56'W</math>. on true line between secs. 8 &amp; 17, with same var.</p>	
40.17	<p>Set hemlock post 3 ft. long, 3 ins. sq., 24 ins. in the ground for <math>\frac{1}{4}</math> sec. cor. marked <math>\frac{1}{4}</math> S. on W. face, from which</p> <p style="padding-left: 40px;">A hemlock, 8 ins. diam., bears N. <math>22^*E</math>. 56 lks. dist. marked <math>\frac{1}{4}</math> S B T.</p> <p style="padding-left: 40px;">A cedar, 20 ins. diam., bears S. <math>17^*E</math>. 32 lks. dist. marked <math>\frac{1}{4}</math> S B T.</p>	
80.34	<p>The cor. to secs. 7, 8, 17 &amp; 18.</p> <p>Land, mountainous.</p> <p>Spil, 3rd rate.</p>	