

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 4 W.

CHAINS

General Description

The land in this township is mostly hilly in the surveyed parts. The timber is principally scattering Fir and Oak. The prairie is rolling or hilly and well suited for agriculture. The NE portion is mountainous and unfit for settlement or cultivation and so steep and rugged as to be almost entirely inaccessible. Most of the valuable land is claimed by actual settler.

Subdivisions of T. 24 S., R. 4 W.
As Surveyed By Oscar F. Thiel, Deputy Surveyor, under
Contract No. 658
Dated May 21, 1896

From the cor. to secs. 23, 24, 25 & 26 which I reestablished by setting a Fir Post 3 ft. long 4 ins. sq., 24 ins. in the ground marked

T 24 S S 24 on NE

R 4 W S 25 on SE

S 26 on SW and

S 23 on NW faces with 2 notches on S and 1 notch on E faces, and witnessed as described by the surveyor general I run

East on Random line bet. secs. 24 & 25

40.00 Set Temp. $\frac{1}{4}$ sec. cor.

80.17 Intersect E bdy. of tp. ^{23.42 chains} 23 42 chs. S of cor. of secs.

19, 24, 25 & 30 which is a Cedar Post 24 ins. high, 4 ins. sq. firmly set, marked and witnessed as described by the surveyor general, except the NW & NE witness trees were blazed but not marked. At intersection set a sandstone 12x8x6 ins. 8 ins. in the ground for closing cor. of secs. 24 & 25 marked CC on W with 2 grooves on S and 4 grooves on N faces from which

A Hemlock, 16 ins. diam., bears N.65*W., 29 lks. dist., Marked T 24 S R 4 W S 24 B T

A Hemlock, 8 ins. diam., bears S61*W., 54 lks. dist. Marked T 24 S R 4 W S 25 B T

See Suppl. Notes. page 3076