

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 4 W.

CHAINS

Timber, Fir, Cedar, Hemlock
Mountainous or heavily timbered land, 80.17 chs. sec.
line and 23.42 chs. closing line

September 16, 1896

At the cor. of secs. 13, 14, 23 & 24 which I reestablish
by setting a Laurel post 3 ft. long, 4 ins. sq., 24 ins.
in the ground marked

T 24 S S 13 on NE

R 4 W S 24 on SE

S 23 on SW and S 14 on NW faces with 3 notches on S
and 1 notch on E edges and witnessed as described
by the surveyor general; thence I run

East on random line bet. secs. 13 & 24

40.00 Set Temp. $\frac{1}{4}$ sec. cor.

79.35 Intersect E bdy. of Tp. , 270 lks. N of cor. of secs. 13,
24, 18 & 19 which is a chitten post, 2 ft. high, 4 ins.
sq. firmly set, marked and witnessed as described by the
surveyor general

At the point of intersection I set a Hemlock Post 3 ft.
long, 4 ins. sq., 24 ins. in the ground for closing cor.
of secs. 13 & 24, marked

CCT 24 S R 4 W on W

S 13 on N and

S 24 on S faces with 3 grooves on S and N faces,
from which

A Fir, 24 ins. diam., bears N.29 $\frac{1}{2}$ *W., 9 lks. dist.

Marked T 24 S R 4 W S 13 B T

A Fir, 24 ins. diam., bears S.14*W., 11 lks. dist.

Marked T 24 S R 4 W S 24 B T

All marks on old post and witness trees referring to the
new work were effaced or corrected

Thence I run

West on true line bet. secs. 13 & 24

Descend Mountain heavily covered by Fir Timber, bears
N and S

See Suppl. Notes.