

Subdivisions of T. 24 S., R. 4 W.

CHAINS

43.20 Top of Spur and a well travelled trail, both bearing
N & S 75 ft. above $\frac{1}{4}$ sec. cor.
Begin steep descent of W slope

57.50 A Stream, 3 lks. wide, course S 300 ft. below top of Spur

64.50 Begin ascent of Mountain

77.00 Top of Ridge bears NE & SW 250 ft. above stream; begin
descent

79.56 The cor. of secs. 11, 12, 13 & 14, 30 ft. below top of
Ridge
Land Mountainous
Soil, gravelly, 3rd. rate
Timber, Fir, Cedar, Hemlock
Mountainous or heavily timbered Land, 79.56 chs. sec. line
and 4.45 chs. closing line

September 18, 1896

From the established $\frac{1}{16}$ sec. cor. on the E $\frac{1}{2}$ of the line
bet. secs. 2 & 11 which is a badly decayed Fir Post, marked
and witnessed as described by the surveyor general, I
run

East on true line bet. secs. 2 & 11

Very steep ascent of a rocky W slope covered heavily with
Fir Timber

4.25 A Branch 2 lks. wide, course NW, 50 ft. below $\frac{1}{16}$ sec.
cor.

6.60 Top of ridge bears N & S 200 ft. above branch
Begin slight descent of S slope

20.00 A Point 120 ft. below top of ridge, I set an Alder Post
3 ft. long 4 ins. sq. 24 ins. in the ground for cor. of
secs. 1, 2, 11 & 12 marked T 24 S S 1 on NE; R 4 W S 12 on
SE; S 11 on SW and S 2 on NW faces with 1 notch on E
and 5 notches on S edges from which

A Fir, 8 ins. diam., bears N. $32\frac{1}{2}^{\circ}$ E., 11 lks. dist.
Marked T 24 S R 4 W S 1 B T

A Fir, 30 ins. diam., bears S. $68\frac{1}{2}^{\circ}$ E., 18 lks. dist.
Marked T 24 S R 4 W S 12 B T