

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 4 W.

CHAINS

Keep on descending S slope

60.10 A Branch, 4 lks. wide, course E., 150 ft. below top of
ridge

Along a bench of Fine Fir Timber bears E & W

71.70 A Branch 3 lks. wide, course E

Begin to ascend

76.60 Top of Spur, bears E & W, 50 ft. above branch

Begin to descend

79.10 A point 40 ft. below top of spur and the cor. of secs. 3
4, 9 & 10

Land Mountainous

Soil, gravelly loam, 3rd. rate

Timber, Fir, Cedar, Hemlock

Mountainous or heavily timbered land, sec. line 79.10 chs.
and 2.90 chs. closing line

September 25, 1896

AT the cor. of secs. 4, 5, 8 & 9

I run

N.0*2'W., on a Random line bet. secs. 4 & 5

40.00 Set Temp. $\frac{1}{2}$ sec. cor.

79.34 Intersect N bdy. of Tp., 271 lks. west of cor. of secs. 4,
5, 32 & 33 which I reestablished by setting a sandstone
6x8x12 ins. 8 ins. in the ground marked with 4 notches
on E and 2 notches on W edges and witnessed as described
by the surveyor general

At the intersection I set a Fir Post 3 ft. long, 4 ins.

sq. 24 ins. in the ground for closing cor. of secs. 4 &

5 marked C C T 24 S R 4 W on S; S 4 on E and S 5 on W

faces with 4 grooves on E and 2 grooves on W face from which

A Maple, 30 ins. diam., bears S.40*E., 36 lks. dist.

Marked T 24 S R 4 W S 4 B T

A Maple, 12 ins. diam., bears S.72*W., 42 lks. dist.

Marked T 24 S R 4 W S 5 B T

All marks on the old witness trees referring to the new
work were effaced or corrected

See
Suppl.
Notes