

County Surveyor's Record, Douglas County, Oregon

South Bdy. of T. 24 S., R. 6 W.

CHAINS		
43.40	A stream 3 lks. wide, course S.70°E	
67.00	A stream 3 lks. wide, course N.70°E	+150
80.00	Set post cor. to secs. 31, 32, 5 & 6, from which	+200
	A fir, 6 ins. diam., bears N.32 $\frac{1}{2}$ °E., 54 lks. dist.	
	A fir, 14 ins. diam., bears N.13°W., 58 lks. dist.	
	A Y oak, 12 ins. diam., bears S.74°W., 136 lks. dist.	
	A fir, 15 ins. diam., bears S.6°E., 155 lks. dist.	
	East 51 chains runs along the valley of a small stream	
	Balance, hilly	
	Timber, fir, oak & laurel	
	Undergrowth, fern, briar, fir, ninebark, hazel etc.	
	Soil, 2nd rate	
	S.89°54'W on south boundary of sec. 31	
	Va. 18°55'E	
7.50	Top of ridge, North & South	+150
26.90	A stream 3 lks. wide, course SE	-50
40.00	Set $\frac{1}{4}$ sec. post, from which	+400
	A fir, 15 ins. diam., bears S.11 $\frac{1}{2}$ °W., 83 lks. dist.	
	A fir, 18 ins. diam., bears N.19°W., 108 lks. dist.	
	Va. 18°55'E	
64.00	Summit of mountain N & S	+1200
	Begin to descend Western slope	
81.75	To township corner	-500
	Land, all mountains	
	Soil, 3rd rate	
	Timber, fir, laurel & etc.	
	Undergrowth, hazel, ninebark, laurel, briar, fern & etc.	
	May 23, 1853	
	General Description	
	The north, west & south lines of this township run	
	through rough & broken mountains from 500 to 2000 ft.	
	high cut up by ravines and streams	