

County Surveyor's Record, Douglas County, Oregon

South Bdy. of T. 24 S., R. 6 W.

CHAINS

Timber, fir, maple, laurel, chinquapin, and etc.

Undergrowth, hazel, vine-maple, briar and etc.

The mountains are very steep and almost inaccessible and
in many places even dangerous to pass.

About half of the township on the SE is good for cultivation
This part
including Green Valley one of the finest we have seen
here, though small, is already settled & will eventually
all be settled

We were employed 14 days in running the Exterior lines,
and lay out, half of the time at nights

It being impossible to pack animals through, we even pack
our bedclothing ourselves.

The whole township seems to rest on a bed of sand rock
projecting in many places 200 and 300 ft. high on
perpendicular cliffs.

Subdivisions of T. 24 S., R. 6 W.
as Surveyed by Robert Elder and Henry S. Gile,
Deputy Surveyors, under Contract No. 31
Dated April 7, 1853

North between Sections 35 and 36

Va. 18°35'E

15.00	Leave Oak openings and enter prairie NW & SE	-75
35.00	A road NW & SE	
40.00	Set $\frac{1}{4}$ post, from which A W oak, 11 ins., bears S.34°W., 469 lks. dist. Made trench as per instructions	
61.00	A house bears East about 5 chs.	-40
67.00	A house bears S.58°W., about 15 chs. Leave prairie and enter brush skirting swail.	
70.25	A stream 15 lks. wide, course SE Leave brush	
72.25	Enter field course NW & SE	
76.50	Leave field course NE & SW	