

Subdivisions of T. 24 S., R. 6 W.

CHAINS

A fir, 15 ins. diam., bears S.67*E., 238 lks. dist.

This tree has been burned down, but the stump is standing, showing scars where marks were made.

Marks burned out

A W oak, 12 ins. diam., bears N.40*W., 37 lks. dist.

Marked T 24 S R 7 W S 13 B T

A W oak, 5 ins. diam., bears S.44*W., 103 lks. dist.

This tree has fallen down and is much decayed

Marked new bearing trees as follows

A fir, 38 ins. diam., bears N.86*50'E., 337 lks.

dist. Marked T 24 S R 6 W S 18 B T

A fir, 20 ins. diam., bears S.66*E., 236 lks. dist.

Marked T 24 S R 6 W S 19 B T

A W oak, 8 ins. diam., bears S.62*25'W. 287 lks.

dist. Marked T 24 S R 7 W S 25 B T

Thence I run

N.89*43'E. on true line bet. secs. 18 & 19

Va. 20*52'E.

3.50	Enter timbers. Steep South slope	
9.00	Stream 3 lks. wide, course SW	-217
23.00	Top of ridge, course N.25*E. & S.25*W.	+162
25.00	Stream 5 lks. wide, course S.25*W.	-22
	Leave timber and enter brush	
41.00	Leave brush and enter prairie	
42.00	Set a fir post, 4 ft. long, 4 ins. sq. 24 ins. in the ground for 1/4 sec. cor. marked 1/4 S on N side, from which	+450
	A fir, 54 ins. diam., bears N.6*E., 163 lks. dist.	
	Marked 1/4 S B T	
	A B oak, oak, 27 ins. diam., bears S.18*50'E., 187 lks. dist. Marked 1/4 S B T	
48.40	Leave prairie and enter timber	
57.00	Spur of ridge course N & S	+264
	Runs along very steep South slope.	