

Subdivisions of T. 24 S., R. 6 W.

CHAINS	
79.40	A spring bears North 50 lks. dist.
80.70	<p>The cor. to secs. 3, 4, 9 &amp; 10</p> <p>The east half of this mile is along a steep South slope of a mountain, rough and rocky.</p> <p>Soil, nearly all poor, 3rd &amp; 4th rate</p> <p>Heavily timbered with fir and cedar, 80.70 chs.</p> <p>Dense undergrowth of fir, hazel and arrowwood, 80.70 chs.</p> <p>The West half is nearly all on the Northwest slope of a mountain ridge, covered with timber and brush, where there has recently been a large land slide. The surface being very much disturbed and moved NW. The timber is all broken down and lies in all positions, much of it being buried in the earth so that it is now very rough.</p> <p style="text-align: right;">Sept. 1, 1891</p>
	<p>N.89°34'E on random line between secs. 2 &amp; 11</p> <p style="text-align: center;">Va. 20°49'E.</p>
40.00	Set temporary 2 sec. cor.
80.40	<p>Intersect N &amp; S line 48 lks. N of cor. to secs. 1, 2, 11 and 12. Post gone, small stake setting at corner.</p> <p>I set a fir post, 4 ft. long, 4 ins. sq. 24 ins. in the ground for cor. to secs. 1, 2, 11 &amp; 12, marked T 24 S S 1 on NE, R 6 W S 12 on SE, S 11 on SW, and S 2 on NW faces, with 5 notches on the South and 1 notch on the East edges, from which</p> <p style="padding-left: 40px;">A W oak, 18 ins. diam., bears N.86°E., 80 lks. dist.</p> <p style="padding-left: 80px;">Marked T 24 S R 6 W S 1 B T</p> <p style="padding-left: 40px;">A Y oak, 11 ins. diam., bears S.31½°E., 133 lks. dist. Marked T 24 S R 6 W S 12 B T</p> <p style="padding-left: 40px;">A W oak, 20 ins. diam., bears S.76°W., 22 lks. dist.</p> <p style="padding-left: 80px;">Marked T 24 S R 6 W S 11 B T</p> <p style="padding-left: 40px;">A W oak, 8 ins. diam., bears N.45½°W., 239 lks. dist. Marked T 24 S R 6 W S 2 B T</p>