

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 6 W.

CHAINS	<p>Thence I run</p> <p>S.89*54*W. on true line bet. secs. 2 &amp; 11</p> <p style="text-align: right;">Va. 20*49'E.</p>	
3.00	Leave timber and enter prairie	+50
8.00	Gully, course South	-85
9.00	Fence, course N & S, leave prairie and enter fir thicket	
14.00	Descend	+85
17.00	Ascend	-23
26.00	Descend	+150
36.30	Stream 5 lks. wide, course S.70*E.	-120
40.20	<p>Set fir post, 4 ft. long, 4 ins. sq. 24 ins. in the ground</p> <p>for <math>\frac{1}{4}</math> sec. cor. marked <math>\frac{1}{4}</math> S on N face, from which</p> <p>A fir, 20 ins. diam., bears S.67*30*W., 26 lks.</p> <p>dist. Marked <math>\frac{1}{4}</math> S B T</p> <p>A fir, 24 ins. diam., bears N.50*15*E. 43 lks.</p> <p>dist. Marked <math>\frac{1}{4}</math> S B T</p>	+50
64.00	Spur, course N.30*W. & S.30*E.	+346
68.40	Gully, course SE	-20
80.40	The cor. to secs. 2, 3, 10 & 11	+554
	<p>The east half of this mile is on rolling ground.</p> <p>Timbered with fir and oak thickets much of which has been crushed down by snow so that it is almost impenetrable. Large fir trees, scattering. The west half is on SE slope of mountain heavily timbered with fir, cedar &amp; laurel. Dense undergrowth of fir, cedar, hazel, dogwood &amp; laurel. Heavily timbered, 74.40 chs.</p> <p>Land, mountainous, steep and rocky</p> <p>Soil 3rd &amp; 4th rate on W part and 1st &amp; 3rd rate on East portion.</p> <p style="text-align: right;">Aug. 31, 1891</p>	
	<p>N.0*2*W. on random line between secs. 2 &amp; 3</p> <p style="text-align: right;">Va. 20*49'E.</p>	
40.00	Set temporary. $\frac{1}{4}$ sec. cor.	