

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 6 W.

CHAINS	
	Dense undergrowth of fir, hazel, arrowwood and dogwood, 80.00 chs.
	Soil, 2nd rate
	South of the $\frac{1}{4}$ sec. cor. there is a land slide 14.55 chs. across where the surface is very broken and is covered by a very dense growth of fir about 30 yrs. old and very dense undergrowth of hazel, willow, arrowwood, maple & salal.
	Soil, 2nd & 4th rate, 80.00 chs.
	Sept. 1st, 1891
	From cor. to secs. 3, 4, 9 & 10, I run
	N.0°31'E. on random line bet. secs. 3 & 4
	Va. 20°40'E.
40.00	Set temporary $\frac{1}{4}$ sec. cor.
80.20	Intersect North line of Tp. at cor. to secs. 3, 4, 33 & 34
	Post gone, bearing trees all down. Stump of one in place with marks. Two others uprooted but not decayed, as is also sight trees 36 lks. dist. east. Notches plainly visible. Reestablished same by setting a yew post, 4 ft. long, 4 ins. sq. 24 ins. in the ground, for cor. to secs. 3, 4, 33 & 34, marked T 23 S S 34 on NE, T 24 S S 3 on SE, R 6 W S 4 on SW, and S 33 on NW faces with 6 notches on the S and 3 notches on the E edges, from which
	The stump of original bearing tree, 40 ins. diam., bears S.71°W., 17 lks. dist. Marked T 24 S R 6 W S 4 B T
	Take new bearing trees as follows:
	A fir, 62 ins. diam., bears N.48°15'E., 69 lks. dist. Marked T 23 S R 6 W S 34 B T
	A fir, 5 ins. diam., bears S.31°10'E., 48 lks. dist. Marked T 24 S R 6 W S 3 B T