

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 24 S., R. 6 W.

CHAINS	
79.58	<p>Intersect Tp. line. Set temp. cor.</p> <p>All traces of cor. and bearing trees to secs. 4, 5, 32 &amp; 33, having been destroyed by forest fires. I proceed to reestablish same by re-running Tp. line on N. Bdy. of secs. 4 &amp; 5</p> <p>From the cor. to secs. 5, 6, 31 &amp; 32 on N. Bdy. of Tp. which cor. I reestablished by setting a cedar post, 4 ft. long, 4 ins. sq. 24 ins. in the ground, marked T 23 S S 32 on NE, T 24 S S 5 on SE, R 6 W S 6 on SW, and S 31 on NW face with 6 notches on S &amp; 5 notches on E edges from which original bearing trees</p> <p style="padding-left: 40px;">A fir, 15 ins. diam., bears N.22*E., 53 lks. dist. Marked T 23 S R 6 W S 32 B T</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears S.47*E., 10 lks. dist. Marked T 24 S R 6 W S 5 B T</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears S.57*W., 8 lks. dist. Marked T 24 S R 6 W S 6 B T</p> <p style="padding-left: 40px;">A fir, 16 ins. diam., bears N.62*W., 60 lks. dist. Marked T 23 S R 6 W S 31 B T</p>
	Thence I run
	East on N. bdy. of sec. 5 to reestablish lost corners
	Va. 20*42'E
2.00	Top of spur, course NE & SW
8.75	Stream 2 lks. wide, course NE
12.00	Spur, course NE & SW
27.30	Bear Creek, 15 lks. wide, Course South
34.66	Sight tree on line
40.00	<p>To <math>\frac{1}{4}</math> sec. cor; post gone reestablish same by setting a fir post, 4 ft. long, 4 ins. sq. 24 ins. in the ground, for <math>\frac{1}{4}</math> sec. cor. marked <math>\frac{1}{4}</math> S on N face, from which</p> <p style="padding-left: 40px;">Stump of original bearing tree, bears S.3*W., 31 lks. dist.</p>