

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 6 W.

CHAINS	<p>A fir, 8 ins. diam., bears N.86*E., 35 lks. dist. Marked T 24 S R 6 W S 7 B T</p> <p>A laurel, 12 ins. diam., bears S.72*E., 23 lks. dist. Marked T 24 S R 6 W S 18 B T</p> <p>A laurel, 12 ins. diam., bears S.76*W., 35 lks. dist. Marked T 24 S R 7 W S 13 B T</p> <p>A laurel, 8 ins. diam., bears N.25*W., 22 lks. dist. Marked T 24 S R 7 W S 12 B T</p>	
	<p>Thence I run N.89*55'E. on true line bet. secs. 7 & 18 Descend</p>	
	Va. 20*45'E	
14.00	Foot of descent	-52
16.00	Spur, course N & S	+173
19.00	Gully, course N	-117
22.00	Spur, course N.20*E. & S.20*W. Descend	+103
27.00	Foot of descent	-55
	Ascend	
30.00	Summit of rise	+32
39.00	Gully, course NE	-404
41.94	<p>Set cedar post, 4 ft. long, 4 ins. sq. 24 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S on N face, from which</p>	
	<p>A fir, 21 ins. diam., bears N.42*15'W., 10 lks. dist. Marked $\frac{1}{4}$ S B T</p>	
	<p>A fir, 36 ins. diam., bears S.51*W., 43 lks. dist. mkd. $\frac{1}{4}$ S B T.</p>	
46.00	Spur, course N & S	+77
53.04	Stream 4 lks. wide, course NW	-186
81.94	To cor. to secs. 7, 8, 17 & 18	+748
	<p>Heavily timbered with fir & cedar, which has been killed in place by fire, 81.94 chs.</p>	
	<p>Dense undergrowth of fir, cedar, hazel, arrow-wood, salal, ferns, briars and vine-maple, 81.94 chs.</p>	