

Exterior Boundaries of T 24 S., R 7 W., W.M.

CHAINS

marked T 24 SR7 W S 36 B T.

A Fir, 20 ins. diam., bears N.50*W., 34 lks. dist.,

marked T 24 S R 7 W S 25 E T.

The true bearing of this line is north and the length, 80.80 chs., instead of 80.00 chs., as stated in reference notes.

Land mountainous and heavily timbered with fir.

6 miles, 6.18 chs. of these lines run over mountainous lands, or through timber or dense underbrush.

GENERAL DESCRIPTION:

The greater portion of this township is mountainous and broken, and is covered with a dense growth of fir and cedar timber of fair quality.

There is some rich bottom land along the Umpqua River, and some of the creeks flowing into it.

There is abundance of pure water in the numerous springs and streams.

W. R Whipple.

U.S. Deputy Surveyor.

Subdivisions of T 24 S R 7 W., W.M., as surveyed by same Deputy, same Contract.

Begin at cor. to secs. 35 & 36, 1 & 2, on S. bdy. of Tp. N.0*1'W., bet. secs. 35 and 36.

Va. 20*38'E.

Ascend over W slope.

- 16.00 Top of spur, course W., about 100 ft. above cor.
- 17.25 Stream, 1 lk.wide, course West.
- 26.15 Stream, 1 lk. wide, course NW.
- 29.50 Stream, 2 lks. wide, course SW.
- 33.30 Stream, 3 lks. wide, course S.20*W., ascend.
- 40.00 Set a post, 3 ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on W face, from which