

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 24 S., R. 8 W.

CHAINS			
			Va.19*E.
18.00	Enter bottom, course NW and SE.		-100
26.25	Creek, 50 lks. wide, course ESE		-10
36.00	Branch, 1 lk. wide, course SE.		+200
40.00	Set qr. sec. post, _____, from which		+50
	An alder, 6 ins. diam., bears N.80*W., 23 lks. dist.		
	An alder, 12 ins. diam., bears N.30*E., 56 lks. dist.		
	Land, hilly, 3d rate.		
	Timber, fir, laurel and maple.		
	Not deemed fit for cultivation farther S.		
	West, bet. secs. 26 and 35.		
			Va.19*E.
7.50	Enter bottom, course N and S.		-100
12.25	Creek, 50 lks. wide, course S.		level
12.25	Leave bottom and commence ascending hill.		
35.35	Branch, 15 lks. wide, course SE.		+25
35.80	Leave same.		
40.00	Set qr. sec. post, _____, from which		+10
	A maple, 12 ins. diam., bears N.70*W., 30 lks. dist.		
	A cedar, 10 ins. diam., bears S.40*E., 58 lks. dist.		
	Land, about the same as last half mile. Land, West of this, too rough for cultivation.		
	North, bet. secs. 25 and 26.		
			Va.19*E.
37.90	Branch, 5 lks. wide, course SW.		+200
40.00	Set qr. sec. post, _____, from which		+50
	A hemlock, 10 ins. diam., bears N.35*E., 6 lks. dist.		
	A hemlock, 10 ins. diam., bears N.64*W., 14 lks. dist.		
53.45	Branch, 1 lk. wide, course SE.		+300
73.50	Summit of mountain.		+400
80.00	Marked a cedar, 6 ins. diam., for cor. secs. 23, 24, 25 and 26, _____, from which		-150