

County Surveyor's Record, Douglas County, Oregon

N. Bdy. of
Retracing of T. 25 S., R. 8 W.

CHAINS

80.00 Corner to Secs. 1 and 2 & 35 and 36. Found post standing and in good condition, also the following witness trees:

Fir, 12 ins. diam., bears N.40*E., 15 lks. dist.

Fir, 6 ins. diam., bears S.65*E., 17 lks. dist.

Fir, 40 ins. diam., bears S.5*W., 20 lks. dist.

Fir, 48 ins. diam., bears N.45*W., 23 lks. dist.

July 9th, 1881.

West, on North boundary Sec. 2.

Va. 19*E.

40.00 Found $\frac{1}{4}$ post standing and in good condition. Also witness trees, which are:

A Fir, 14 ins. diam., bears S.45*E., 26 lks. dist.

A Fir, 24 ins. diam., bears N.8*W., 28 lks. dist.

80.00 Corner to Secs. 2 and 3 & 34 and 35. The corner is a Fir tree, 36 ins. in diam., from which a

Fir, 60 ins. diam., bears N.64*E., 52 lks. dist.

Fir, 60 ins. diam., bears S.30*E., 38 lks. dist.

Fir, 12 ins. diam., bears S.15*W., 29 lks. dist.

Fir, 8 ins. diam., bears N.8*W., 22 lks. dist.

July 11th, 1881.

Exteriors of T. 24 S., R. 8 W., and
Resurvey of South Boundary of T. 24 S., R. 8 W.
As surveyed by Henry L. Chandler, Deputy Surveyor,
under Contract N. 619, dated June 5, 1893.

From the closing cor. to Tps. 24 S., R's. 7 and 8 W.

I run

West on a random line along the North boundary of Tp.

24 S., Range 8 W. and at 5 miles, 59 chs. and 33 lks.,

I fall 17.97 chs. N. of cor. to Tps. 23 and 24 S.,

R's. 8 and 9 W.

The above closing shows a large error to exist in both latitudes and departures in the exterior lines of this Tp..