

Resurvey of West Boundary T. 24 S., R. 8 W.

CHAINS

A Fir, 24 ins. diam., bears S.88*E., 38 lks.

dist., marked T 24 S R 8 W S 19 - B T.

A Fir, 24 ins. diam., bears S.40*W., 13 lks.

dist., marked T 24 S R 9 W S 24 - B T.

A Fir, 16 ins. diam., bears N.45*W., 17 lks.

dist., marked T 24 S R 9 W S 13 - B T.

I destroy marks on both cor. tree and bearing trees referring to Secs. 18 and 19.

40.00 Set a post 4 ft. long, 4 ins. sq., 24 ins. in the ground for cor. to secs. 18 and 19, T.24 S., R. 8 W., marked T 24 S S 18 on NE., and R 8 W S 19 on SE. faces, with 3 notches on North and South edges, from which

A Fir, 24 ins. diam., bears N.76*E., 25 lks.

dist., marked T 24 S R 8 W S 18 - B T.

A Fir, 18 ins. diam., bears S.84*E., 21 lks.

dist., marked T 24 S R 8 W S 19 - B T.

A Fir, 30 ins. diam., bears S.69*W., 38 lks.

dist., marked T 24 S R 8 W S 18 and 19 - B T.

Land, broken.

Soil, 2nd and 4th rate.

Heavily timbered with Fir and Hemlock. 40.00 chs.

Dense undergrowth of salal, hemlock and arrow wood.

40.00 chs.

North, on West boundary Sec. 18.

Va. 20*E.

Over broken land, through heavy timber and dense undergrowth.

5.00 Trail on top of spur, course East and West.

34.16 The $\frac{1}{4}$ sec. cor. on East bdy. Sec. 13, which is a post 4 ins. sq., marked $\frac{1}{4}$ S on W., face, from which