

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 8 W.

CHAINS
40.00

Set a sandstone 18 x 16 x 8 ins., 12 ins. in the ground for $\frac{1}{2}$ sec. cor., marked $\frac{1}{2}$ on West face, from which

A Fir, 40 ins. diam., bears N.57*E., 14 lks. dist., marked $\frac{1}{2}$ S B T.

A Fir, 30 ins. diam., bears N.20*W., 30 lks. dist., marked $\frac{1}{2}$ S B T.

80.00

Set a sandstone 14 x 12 x 7 ins., 9 ins. in the ground for cor. to Secs. 29, 30, 31 and 32, marked with 1 notch on South and 5 notches on East edges, from which

A Laurel, 12 ins. diam., bears N.34*E., 36 lks. dist., marked T 24 S R 8 W S 29 - B T.

A Cedar, 18 ins. diam., bears S.65*E., 37 lks. dist., marked T 24 S R 8 W S 32 - B T.

A Laurel, 16 ins. diam., bears S.60*W., 20 lks. dist., marked T 24 S R 8 W S 31 - B T.

A Fir, 12 ins. diam., bears N.13*W., 31 lks. dist., marked T 24 S R 8 W S 30 - B T.

Land, mountainous. 80.00 chs.

Soil, sandy and rocky, 3rd and 4th rate.

Heavily timbered with Hemlock, Fir and Cedar. 80.00 chs.

Dense undergrowth of vinemaple, salal and hazel.

80.00 chs.

East, on a random line bet. Secs. 29 and 32.

Va. 20*E.

40.00

Set temporary $\frac{1}{2}$ sec. cor.

79.70

Intersect E. & W. line, 20 lks. South of the cor. to Secs. 28, 29, 32 and 33.

Thence I run

S.89*51'W., on a true line bet. Secs. 29 and 32.

Va. 20*E.

Through heavy timber and dense undergrowth.