

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 8 W.

CHAINS	<p>S.89°53'E., on a true line bet. Secs. 7 and 18.</p> <p style="text-align: right;">Va. 20°E.</p> <p>Descend through heavy timber and dense undergrowth about 150 ft. to</p> <p>11.00 A Creek, 15 lks. wide, flows SE.</p> <p>20.60 Set a post 3½ ft. long, 3 ins. sq., 24 ins. in the ground for ¼ sec. cor., marked ¼ S. on N. face, from which</p> <p style="padding-left: 40px;">A Fir, 24 ins. diam., bears N.42°E., 17 lks. dist., marked ¼ S B T.</p> <p style="padding-left: 40px;">A Fir, 24 ins. diam., bears S.45°E., 14 lks. dist., marked ¼ S. B T.</p> <p>25.00 Top of spur, course SW., about 150 ft. above creek.</p> <p>Descend about 120 ft. to</p> <p>35.00 A Creek, 10 lks. wide, flows SW.</p> <p>Ascend about 200 ft. to</p> <p>60.60 The cor. to Secs. 7, 8, 17 and 18.</p> <p>Land, mountainous. 60.60 chs.</p> <p>Soil, sandy and rocky, 2nd and 4th rate.</p> <p>Heavily timbered with Fir and Hemlock. 60.60 chs.</p> <p>Dense undergrowth of salal and rhododendron. 60.60 chs.</p> <p style="text-align: right;">June 26th, 1894.</p>
--------	---

N.0°4'W., bet. Secs. 7 and 8.

Va. 20°E.

CHAINS	<p>Ascend through heavy timber and dense undergrowth about 70 ft. to</p> <p>6.00 Top of ridge, course SW.</p> <p>Descend about 200 ft. to</p> <p>29.25 Spring branch, 3 lks. wide, flows SW.</p> <p>Ascend about 250 ft. to</p> <p>40.00 Top of ridge, course SW.</p> <p>Set a post 3½ ft. long, 3 ins. sq., 24 ins. in the ground for ¼ sec. cor., marked ¼ S. on W. face, from which</p>
--------	--