

## Retracements of South Boundary T. 24 S., R. 8 W.

## CHAINS

- 65.50 Top of ridge, bears N. and S. descend.
- 70.40 Old sec. cor. in place; post and bearing tree marked and witnessed as described by the Surveyor General. I destroy the post, and cut out all marks on bearing trees.
- 84.75 Cor. of Secs. 5, 6, 31 and 32 established in 1894, Contract No. 619, and which is a post, firmly set, marked and witnessed as described by the Surveyor General, bears N.95 lks. dist. I destroy marks on post and bearing trees referring to Secs. 5 and 6. The true course of this line is N.89°21'W., and the length is 84.75 chs.

Land, mountainous.

Soil, 2nd and 3rd rate.

Timber, heavy Fir, Hemlock and Cedar.

Dense undergrowth of little fir, hemlock and rhododendron.

Mountainous land, covered with heavy timber and dense undergrowth and exceptionally difficult to survey.

84.75 chs.

June 19th, 1911.

At the cor. of Secs. 31 and 32, on the S. bdy. of T. 24 S., R. 8 W.

Thence I run

West, on retracement of S. bdy. of Sec. 31

Descend through heavy timber and dense undergrowth.

- 4.30 Creek, 2 lks. wide, course NW.
- 6.10 Creek, 2 lks. wide, course NW.
- 8.30 Creek, 2 lks. wide, course NW.
- 19.90 Creek, 1 lk. wide, course NW.
- 21.86 Old  $\frac{1}{4}$  sec. cor. on S. bdy. of Sec. 31, bears S. 10 lks. I destroy this corner.