

Subdivisions of T. 24 S., R. 9 W., W. M.

CHAINS	
	<p>Line, runs along South slope of spur, broken, brushey, 3rd rate.</p> <p>Descriptions of timbers and underbrush, unchanged.</p>
	<p>North, on line between Secs. 22 &amp; 23. <span style="float: right;">Va. 18°30'E.</span></p>
15.00	Top of high knoll.
19.25	Top of rocky precipice, 50 feet.
40.00	<p>Set cedar post 5 feet long, 5 ins. in dia., 20 ins. in ground, for the <math>\frac{1}{4}</math> Sec. corner between Secs. 22 &amp; 23, from which a,</p> <p style="padding-left: 40px;">Fir, 24 ins. dia., bears S.57°E., 18 lks. dist.</p> <p style="padding-left: 40px;">Fir, 36 ins. dia., bears S.25°W., 31 lks. dist.</p>
41.70	A creek, 3 lks. wide, course NW.
80.00	<p>Set maple post 5 feet long, 5 ins. dia., 20 ins. in ground for the corner to Secs. 14, 15, 22 &amp; 23, from which a.</p> <p style="padding-left: 40px;">Fir, 36 ins. dia., bears N.50°E., 40 lks. dist.</p> <p style="padding-left: 40px;">Fir, 16 ins. dia., bears S.74°E., 45 lks. dist.</p> <p style="padding-left: 40px;">Fir, 30 ins. dia., bears S.47°E., 18 lks. dist.</p> <p style="padding-left: 40px;">Fir, 12 ins. dia., bears N.32°W., 40 lks. dist.</p> <p>Land, broken; 3rd rate.</p> <p>Description of timbers unchanged; 1st class.</p> <p style="text-align: center;">May 4th 1879.</p>
	<p>East, on random line between Secs. 14 &amp; 23. <span style="float: right;">Va. 18°30'E.</span></p>
40.00	Set temporary $\frac{1}{4}$ Sec. corner.
80.82	<p>Intersect line 120 lks. south of corner.</p> <p>S.89°09'W., on true line between secs. 14 &amp; 23.</p>
22.00	Lake creek, 75 lks. wide, course N.
35.00	Leave bottom lands, course NW. & SE.
40.41	<p>Set Maple post 5 feet long, 5 ins. dia., 20 ins. in ground for the <math>\frac{1}{4}</math> Sec. corner between Secs. 14 &amp; 23, from which a,</p> <p style="padding-left: 40px;">Fir, 18 ins. dia., bears N.20°E., 18 lks. dist.</p> <p style="padding-left: 40px;">Fir, 20 ins. dia., bears S.30°E., 16 lks. dist.</p>