

28

County Surveyor's Record, Douglas County, Oregon

Retracement of the East Boundary of T. 24 S., R. 10 W.,
Same Deputy and Contract.

CHAINS

At the cor. of Tps. 24 and 25 S., Rs. 9 and 10 W.

Thence I run

North, on a blank line retracing the E. bdy. of Sec. 36.

Ascend over mountainous land through heavy timber and
dense undergrowth, 500 ft.

39.00 Summit of ridge slopes SE.

Descend.

39.77 The old corner being gone, I locate the exact point by

reference to the original bearing trees where I

Set a fir post, 3 ft. long, 4 ins. sq., 24 ins. in the

ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on W. face and

witnessed as described by the Surveyor General.

The $\frac{1}{4}$ sec. cor. bears E. 100 lks. dis. therefore the

true bearing of this line is N.1*26'E.

From the $\frac{1}{4}$ sec. cor. on E. bdy. of sec. 36, T. 24 S.,

Range, 10 W.

I run

North, on a blank line retracing the E. bdy. of sec. 36.

Continue descent.

~~Continue descent.~~

14.45 A branch 4 lks. wide, 400 ft. below summit of ridge;

course S.60'E.

38.72 The cor. of secs. 25 and 36, heretofore described, bears

East 58 lks. dis.

Therefore, the true bearing of this line is N.0*51'E.

The old post not being in a good state of preservation,

I destroy it and ^{at} the exact point.

Set a hemlock post, 3 ft. long, 4 ins. sq., 24 ins. in the

ground for cor. of secs. 25 and 36, T. 24 S., R. 10 W.,

mkd. T 24 S. S. 36 on SW. and

R 10 W S 25 on NW. face, with 1 notch on S., and 5

notches on N. edge.

I obliterate all marks on bearing trees referring to

secs. 30 and 31 R. 9 W.